

## **Report of Load Test**

Report Number: 55108-i	Job Number: 55108	Load Test Certificate. Page1		Date of Report: 19/06/2018	Date of Load Test: 19/07/2018		
Name and address of customer for whom the test was made:  Vertical Leisure Ltd Unit 2, 181 Victoria Road New Barnet Herts			Address of premises at which the examination was made: Bickers Lifting ltd Ivy Farm Works Coddenham Suffolk				
Item ID/ Asset No	Product/Product Description		Working Load Limit	Date of Last thorough Examination	Additional Notes		
хнм-мат-рк	Hammock Materia	al Only (5M) - Pink	TBC	N/A			
Measuring Equipment Used:  RLPT5 5t Loadcell. Serial No. 16155. Calibrated 18-10-17. cert No. 14749							
Notes: Test Scenario:  Aerial hammock will have a tensile load applied along its length. Progressive increase in load until failure							
Name of Report Maker: Authenticator Sig		Authenticator Signature:	:	Name of person authenticating this report:			
Darren Short		M. Ford		Marina Ford			
Name and address of employer of persons making and authenticating this report:							

Bickers Lifting Ltd, Ivy Farm works, High Street, Coddenham, Suffolk. IP6 9QX. Registered in England 3830215.
761 705 www.bickerslifting.co.uk sales@bickerslifting.co.uk

Bickers Lifting Ltd, Ivy Farm works, High Street, Coddenham, Suffolk. IP6 9QX

Tel: 01449



## **Report of Load Test**

Report Number: 55108-i	Job Number: 55108	Detailed Results. Page 2		Date of Report: 19/06/2018	Date of Load Test: 19/07/2018
Name and address of customer for whom the test was made:  Vertical Leisure Ltd Unit 2, 181 Victoria Road New Barnet Herts			Address of premises at which the examination was made: Bickers Lifting Itd Ivy Farm Works Coddenham Suffolk		
Item ID/ Asset No	Product/Product Description		Working Load Limit	Date of Last thorough Examination	Additional Notes
ХНМ-МАТ-РК	Hammock Materia	al Only (5M) - Pink	ТВС	N/A	

## Test Details:

Aerial hammock will be attached to the tensile test rigs using "figure 8" hardware and "tied" as they would be when in use. Load to be applied progressively until failure. Hammock will then be "doubled" and "tied" as they would be used. The test will then be repeated and failure points noted.

## Results:

Mode	Load Applied applied	Failure	Notes
Single	1300kgs	Tear	
Double	2000kgs	Tear	
	·		

Bickers Lifting Ltd, Ivy Farm works, High Street, Coddenham, Suffolk. IP6 9QX. Registered in England 3830215.
761 705 www.bickerslifting.co.uk sales@bickerslifting.co.uk

Tel: 01449